USEPA 290 BROADWAY

NY, NY

NOTIFICATION OF DEMOLITION AND RENOVATION PAL JOB # 15-9017

Operator Project #	Postmark	Date Rec	Received Notification			ication	#	
TYPE OF NOTIFICATION (O. S								
TYPE OF NOTIFICATION (O-C	original, R-Received, C-Canc	elled): R -	Add Varia	ance Inform	ation			
FACILITY INFORMATION (Ide OWNER NAME: NYCMTA	ntiry Owner, Removal Contr	ractor and C	other Operation	ator):				
Address: 2 Broadway								
City: New York			Ct					
Contact Name: Joseph Zamor		State: NY Zip: 10004						
PEMOVAL CONTRACTOR: DAL	-1/1-/- DAI		Te	lephone: 646-527-1801				
REMOVAL CONTRACTOR: PAL Address: 11-02 Queens Plaza	Courth South	. d/b/a PAL	Environme	ental Services				
City: Long Island City	South						_	
Contact Name: Devin Jones					State: NY Zip: 11101			
OTHER CONTRACTOR:		Telephone: 718-349-0900						
Address:						1		
City:				T 61 .				
Contact Name:				State		Zip:		
	o Ordered Dome D Dom	and a F			Telephone:			
TYPE OF OPERATION (D-Dem- IS ASBESTOS PRESENT? (YES	NO) VES	ovation, E-E	mergency	Renovation:	R			
15 ASDESTOS FRESENT! (TES	NO) TES							
FACILITY DESCRIPTION (Include Building Name, Number and Floor or Room Number)								
Building Name: Westchester Yard								
Address: 1384-1480 Waters Pl	ace							
City: Bronx			State: NY			Zip: 10461		
Site Location:								
Building Size:			# of Floors: Age in Years: 50-			Years: 50+		
Present Use: Train Yard			Prior Use: Train Yard					
Procedure, Including Analytical	Method, If Appropriate, Us PLM – Polarized L	sed to Detectight Microso	t the Prese	ence of Asbes	tos Material:			
Approximate amount of asbest	os, R. ACM		Non-Friable Indicate Unit of Measurement			of Mascurament		
Including	to be		Asbestos Material		Below			
 Regulated ACM to be remo 		t	not to be removed		BCIOW			
2. Category I ACM not remove		and the second second	and the second s					
Category II ACM not remo	ved							
			CAT I	CAT II		l	UNIT	
Braided Wire	210				Linear Fee	et: X	Ln M:	
Surface Area: Flashing & Trans	,,,,,				Square Fe	et: X	Square Meter:	
Volume RACM off Facility Comp					CuFt:		Cu M:	
Scheduled Dates Asbestos Removal (mm/dd./yy)			Start: 07/29/2016		Complete	Complete: 07/01/2017		
Scheduled Dates Demo/Renovation (mm/dd./yy)			Start:		Complete	Complete:		

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA								
will be done in accordance with the applicable New York State Industrial Code Rule 56, Site Specific Variance #14-0242 & 14-0244 & 14-0248. Methods will include double bagged for disposal purposes. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITON AND RENOVATION SITE: HEPA Vacs, Micro Traps (Negative Air Pressure) and amended water will be utilized for emissions control. WASTE TRANSPORTER #1 Name: Tri State Transfer Associates Address: 1199 Randall Avenue City: Long Island City Contact Name: Art Contact Name: Jimmy Byrne WASTE TRANSPORTER #2 WASTE TRANSPORTER #2 WASTE TRANSPORTER #2 WASTE TRANSPORTER #2 WASTE TRANSPORTER #3 Name: Art Contact Name	DESCRIPTION OF PLANNED DEMOLITION OR RENOVAT	TON WORK AND METHOD (S) TO BE	IISED: This ashestes abatement project					
DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION AND REMOVATION SITE: HEPA Vacs, Micro Traps (Negative Air Pressure) and amended water will be utilized for emissions control. WASTE TRANSPORTER #1 Name: I'ri State Transfer Associates Address: 1199 Randall Avenue City: Long Island City Contact Name: Jimmy Byrne VASTE TRANSPORTER #2 Name: ATC Address: 199 Randall Avenue City: Long Island City Contact Name: Jimmy Byrne VASTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley Contact Name: Smy Value Vaste: NY Value Vaste: NY Value Value Vaste: NY Value V	will be done in accordance with the applicable New York State Industrial Code Rule 56. Site Specific Variance #14							
DESCRIPTION OF WORK PRACTICES AND ENCINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITON AND RENOVATION SITE: HEPA Vacs, Micro Traps (Negative Air Pressure) and amended water will be utilized for emissions control. WASTE TRANSPORTER #1 Name: Th State Transfer Associates Address: 1199 Randall Avenue (Ity: Long Island City	0242, 14-0244 & 14-0248. Methods will include d	ouble bagged for disposal purpos	ses.					
THE DEMOLITION AND RENOVATION SITE: HEPA Vacs, Micro Traps (Negative Air Pressure) and amended water will be utilized for emissions control. WASTE TRANSPORTER #1 Name: Tri State Transfer Associates Address: 1199 Randall Avenue City: Long Island City Contact Name: Jimmy Byrne WASTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley Contact Name: Kenny Smith Telephone: 718-617-0771 WASTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 10-10 Queens Plaza South City: Long Island City City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) DATI JULY 114-114-114-114-114-114-114-114-114-114	DESCRIPTION OF WORK PRACTICES AND ENGINEERING	G CONTROLS TO BE USED TO PREVE	NT EMISSIONS OF ASRESTOS AT					
WASTE TRANSPORTER #1 Name: Tri State Transfer Associates Address: 1199 Randall Avenue City: Long Island City Vaste: NY Zip: 10474 Contact Name: Jimmy Byrne Vaste: TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley State: NY Zip: Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTIOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON VILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 907/13/2016 Signature of O mer/Operator Date 1 certify that this labove information is correct	THE DEMOLITION AND RENOVATION SITE:							
WASTE TRANSPORTER #1 Name: Tri State Transfer Associates Address: 1199 Randall Avenue City: Long Island City Vaste: NY Zip: 10474 Contact Name: Jimmy Byrne Vaste: TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley Vaste: NY Zip: Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTIOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULLVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON VILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 207/13/2016 Signature of O mer/Operator Date 1 certify that this labove information is correct	HEPA Vacs, Micro Traps (Negative Air Pressure) and amended water will be utilized for emissions control							
Address: 1199 Randall Avenue City: Long Island City Variety State: NY Zip: 10474 Contact Name: Jimmy Byrne Variety Randsporter #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley Contact Name: Kenny Smith Vaste TRANSPORTER #2 Name: Kenny Smith Vaste TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULLVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with ammeded water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 20/113/2016 Signature of Omer/Operator Date 1 certify that this labove information is correct	WASTE TRANSPORTER #1							
City: Long Island City Telephone: 718-617-0771 Contact Name: Jimmy Byrne Telephone: 718-617-0771 WASTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley State: NY Zip: Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: PALL. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unre	Name: Tri State Transfer Associates							
Contact Name: Jimmy Byrne WASTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE Lication: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY. NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA ICERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 107/13/2016 Signature of Omer/Operator Date 1 certify that this bove information is correct	Address: 1199 Randall Avenue							
Contact Name: Jimmy Byrne WASTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY. NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 1 Certify that this bove information is correct 1 Certify that this bove information is correct	City: Long Island City	State: NY	Zip: 10474					
WASTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley Contact Name: Kenny Smith WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 97/13/2016 Signature of Omer/Operator Date I certify that the labove information is correct	Contact Name: Jimmy Byrne							
Address: 2 Moriches Middle Island Road City: Shirley State: NY Zip: Contact Name: Kenny Smith WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 97/13/2016 Signature of Omer/Operator Date I certify that the above information is correct	WASTE TRANSPORTER #2							
City: Shirley Contact Name: Kenny Smith WaSTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OP PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-STIED DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 07/13/2016 Signature of Other/Operator Date 1 certify that the above information is correct	Name: ATC							
Contact Name: Kenny Smith WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City: Long Island	Address: 2 Moriches Middle Island Road							
Contact Name: Kenny Smith WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City City: Long Island City City: Long Island City City: Long Island City City: Long Island City City: Long Island City Cit	City: Shirley	State: NY	Zin:					
WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 07/13/2016 Signature of Other/Operator Date I certify that the labove information is correct	Contact Name: Kenny Smith							
Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 07/13/2016 Signature of Owner/Operator Date		CHILD TO THE PARTY OF THE PARTY	Telephone: 031 321 3030					
Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 07/13/2016 Signature of Owner/Operator Date	Name: P.A.L. Environmental Safety Corp. d/b/a PAL Envi	ironmental Services						
Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 07/13/2016 Signature of Orner/Operator Date I certify that the labove information is correct								
Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 07/13/2016 Signature of Other/Operator Date I certify that the labove information is correct	City: Long Island City	City: Long Island City	City: Long Island City					
Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-STITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O7/13/2016 Signature of Omer/Operator Date O7/13/2016	Telephone: 718-349-0900	, , , , , , , , , , , , , , , , , , , ,	Total Long Loland City					
Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) Signature of Owner/Operator Total Cartify that the above information is correct 07/13/2016	Disposal Facility							
State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O7/13/2016 Signature of Omer/Operator Date O7/13/2016	Name: Minerva Enterprises							
City: Waynesburg FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O7/13/2016 Signature of Omer/Operator Date O7/13/2016	Location: 9000 Minerva Road, SE	Location: 9000 Minerva Roa	ad. SF					
Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 1 Certify that the above information is correct 1 Certify that the above information is correct								
Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O7/13/2016 Signature of Orner/Operator Date I certify that the above information is correct			2.51 11000					
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 07/13/2016 Signature of Other/Operator Date I certify that the above information is correct	Date and Hour of Emergency (mm/dd./yy)							
DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O7/13/2016 Signature of Owner/Operator Date I certify that the above information is correct	Description of the Sudden, Unexpected Event:							
DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O7/13/2016 Signature of Owner/Operator Date I certify that the above information is correct	Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden.							
NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O7/13/2016 Signature of Owner/Operator Date I certify that the labove information is correct	DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY							
unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O7/13/2016 Signature of Owner/Operator Date I certify that the above information is correct 07/13/2016	NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered							
Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O7/13/2016 Signature of Owner/Operator Date I certify that the above information is correct 07/13/2016	unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA							
THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O7/13/2016 Signature of Owner/Operator Date I certify that the above information is correct 07/13/2016	Vacs, to be put in 6 mil poly bags for proper disposal.							
THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O7/13/2016 Signature of Owner/Operator Date I certify that the above information is correct 07/13/2016	I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROV	VISIONS OF THIS REGUALTION (40 C	FT PART 61, SUBPART M), WILL BE ON-					
O7/13/2016 Signature of Owner/Operator Date I certify that the above information is correct 07/13/2016	STIE DOKTING THE DEMOLITION OR RENOVATION AND	EVIDENCE THAT THE REQUIRED TRA	INING HAS REEN ACCOMPLISHED BY					
Signature of Owner/Operator Date I certify that the above information is correct 07/13/2016	THIS PERSON WILL BE AVAILABLE FOR INSPECTION DU	JRING NORMAL BUSINESS HOURS (re	equired 1 year after promulgation)					
Signature of Owner/Operator Date I certify that the above information is correct 07/13/2016	\ \\\	•	, , , , , , , , , , , , , , , , , , , ,					
I certify that the above information is correct 07/13/2016	07/13/2016							
07/13/2016								
O7/13/2016 Signature of Owner/Operator Date	I certify that the above information is correct							
Signature of Owner/Operator Date			40.07					
Signature of Owner/Operator Date	Signature of 07/13/2016							
	Signature of Owner/Operator Date							